

Economy

Facility Floor Sticker

Installation Instructions

Surface Preparation Instructions:

1. Surface temperature should be 40 degrees Fahrenheit or higher.
2. Thoroughly sweep the application area and make sure the area is thoroughly dry for proper adhesion of the floor sticker.
3. If the application area is oily, it may need to be power washed with a commercial degreaser or cleaned with muriatic acid.
4. Avoid applying over oily residues, flaking paint or other foreign substances that will interfere with proper adhesion.

Application Instructions:

- A. Once the application area is prepared, peel the backing paper from the sticker.
- B. Lay it down flat on the selected location.
- C. Smooth by hand from the center to the outer edge. Be sure all edges lay flat then firmly press down from the center out using the supplied squeegee.
- D. Step on the graphic aggressively over the entire surface, especially the edges, to compress the surface, making sure the edges are well adhered.
- E. Avoid harsh cleaning chemicals and intense power washing, to extend the product life.
- F. **IMPORTANT: Do Not Drag Pallets over the Floor Sticker!** Avoid putting the sticker where a forklift wheel will turn on the sticker.

Removal Instructions

- a. This decal is for permanent installation and may be difficult to remove once it is in place.
- b. Peel off at an angle less than 45 degrees for best result.
- c. Use a power washer at a low angle to remove well-worn graphics.
- d. Severely worn-in graphics may require a combination of scraping with a scraper and/or power washing.
- e. If there is an adhesive residue, remove it with cleaning solvents or mineral spirits.

Your Friends at
*New Tech
Graphics*

New Tech Graphics
901-759-0932 - Central Time
1657 Shelby Oaks Drive, Suite 101
Memphis, TN 38134-7436

Memphis, the Heart & Soul of Rock & Roll®

Bringing
You

