## Forklift Tough® Facility Floor Sticker Installation Instructions

**IMPORTANT: DO NOT** Drag Pallets over the Floor Sticker!

**IMPORTANT: DO NOT** Place the sticker where a forklift wheel will turn on the sticker!

**READ ME:** No product, including paint and even the 3M street markers, applied to the floor of a facility will last very long when the pallets are drug on the floor over the installation location. We do not guarantee our floor stickers against dragging pallet damage or when a wheel of a forklift turns directly on top of the sticker. If you have any questions please contact us via email or at 901-759-0932, Central Time. before you proceed with installation.

## Surface Preparation Instructions:

- 1. Surface temperature should be 40 degrees Fahrenheit or higher.
- 2. Thoroughly sweep the application area and make sure the area is thoroughly dry for proper adhesion of the floor sticker.
- 3. If the application area is oily, it may need to be power washed with a commercial degreaser or cleaned with muriatic acid.
- 4. Avoid applying over oily residues, flaking paint or other foreign substances that will interfere with proper adhesion.

## Application Instructions:

- A. Once the application area is prepared, peel the backing paper from the sticker.
- B. Lay it down flat on the selected location.
- C. Smooth by hand from the center to the outer edge. Be sure all edges lay flat then firmly press down from the center out using the supplied squeegee.
- D. Step on the graphic aggressively over the entire surface, especially the edges, to compress the surface, making sure the edges are well adhered.
- E. Avoid harsh cleaning chemicals and intense power washing, to extend the product life.

## Removal Instructions

- a. This decal is for permanent installation and may be difficult to remove once it is in place.
- b. Peel off at an angle less than 45 degrees for best result.
- c. Use a power washer at a low angle to remove well-worn graphics.
- d. Severely worn-in graphics may require a combination of scraping with a scraper and/or power washing.
- e. If there is an adhesive residue, remove it with cleaning solvents or mineral spirits.

